

GREISINGER CLIMATE MEASURING - HYGROMETER /THERMOMETER/BAROMETER

GFTB 200

GFTB-200

Hygrometer / thermometer / barometer

- Designed for measuring air pressure, air humidity and temperature within seconds.
- Electrical isolated interface converter, directly connectable to PC.
- Scope of supply: Device, battery, calibration protocol, manual
- High precision sensors provide remarkable accuracy



Product description

Specifications

Central Material	ABS plastic
Dimensions	106 x 67 x 30 mm
Display	4½ digit LCD, 11mm high
Measuring Application	Temperature, Air Humidity, Air Pressure
Measuring Range: Air Humidity	0.0 ... 100.0 %RH
Measuring Range: Air Pressure	10.0 ... 1100.0 mbar
Measuring Range: Temperature	-25 ... 70°C
Operating temperature	-25 ... 70°C
Power	9 V Battery
Resolution	0.1%RH, 0.1°C or 0.1mbar
Type	Humidity Measuring
Weight	130

