GREISINGER AIR OXYGEN MEASURING DEVICE - WITHOUT SENSOR

GMH 3692, GMH 3695

GMH-3692

Air oxygen measuring device w/o sensor

- Suitable for use in biochemistry, medicine, food technology, air conditioning and ventilation technology and sport
- Sensor connection: 6-pin Mini-DIN-socket (GMH 3695: additional pressure ports)
- Scope of supply: Device, battery, calibration protocol, manual
- Automatic compensation of ambient air via integrated barometer



Product description

Specifications

Battery Life	300
Dimensions	142 x 71 x 26 mm
Display	two 4 digit LCDs, 12.4mm high
Measuring Range: Air Pressure	10 1200 hPa
Measuring Range: Oxygen	0.0 100.0% O ₂ , 0 1100 hPa O ₂
Measuring Range: Temperature	-5.0 50.0°C
Operating temperature	0 50°C
Resolution	Oxygen: $\pm 0.1\%$, Temperature: $\pm 0.1^{\circ}$ C, Air Pressure: ± 3 hPa or 0.1% v.m.w (whichever is higher)
Storage temperature	-20 70°C
Туре	Gas analysis Oxy detector
Weight	160

