

## GREISINGER MANOMETER FOR OVER/UNDER PRESSURE OR PRESSURE DIFFERENCE

GDH 200-07, GDH 200-13

GDH-200-13

Manometer, 0.0 ... 199.9 / 1999 mbar ( $\pm 1999$  mbar)

- Differential and relative pressure measurement
- Sensor: piezoresistive relative pressure sensor
- Scope of supply: Device, battery, calibration protocol, manual
- 3 selectable measuring units: mbar, mmHg, PSI (GDH 200-07 also includes Pa)



### Product description

### Specifications

<b>Battery Life</b>	1200
<b>Dimensions</b>	106 x 67 x 30 mm
<b>Display</b>	3½ digit LCD, 13mm high
<b>Measuring Range: Over/under Pressure</b>	0.0 ... 199.9 / 200 ... 1999 mbar, 0.0 ... 199.9 / 200 ... 1500 mmHg, 0.00 ... 19.99 PSI
<b>Operating temperature</b>	-25 ... 50°C
<b>Resolution</b>	Automatic change 1 / 0.1
<b>Type</b>	Manometer
<b>Weight</b>	135