

GREISINGER MANOMETER FOR OVER/UNDER PRESSURE OR PRESSURE DIFFERENCE

GDH 200-07, GDH 200-13

GDH-200-13

Manometer, 0.0 ... 199.9 / 1999 mbar (± 1999 mbar)

- Differential and relative pressure measurement
- Sensor: piezoresistive relative pressure sensor
- Scope of supply: Device, battery, calibration protocol, manual
- 3 selectable measuring units: mbar, mmHg, PSI (GDH 200-07 also includes Pa)



Product description

Specifications

Battery Life	1200
Central Material	ABS plastic
Dimensions	106 x 67 x 30 mm
Display	3½ digit LCD, 13mm high
Measuring Application	Over/Under Pressure
Measuring Range: Over/under Pressure	0.0 ... 199.9 / 200 ... 1999 mbar, 0.0 ... 199.9 / 200 ... 1500 mmHg, 0.00 ... 19.99 PSI
Operating temperature	-25 ... 50°C
Power	9 V Battery
Resolution	Automatic change 1 / 0.1
Type	Manometer
Weight	135